

Functions

Measuring Mode	Normal, harmonics, integration
Types of Files	Waveform, calculated values, harmonics, settings
Display Screens	Numerical, waveform*, trend, harmonic Bar Graph* * /G6option is required on .
Data Acquisition Interval	50 ms at max. speed. - The data storage period can be any custom settings (more than 20 seconds) and the data update rate of the body. - Depends on your PC's performance.*When the WT3000E data update interval is shorter than the time it takes for the software to collect one set of measured data, there will be pieces of data that the software will not collect.

List of functions

Display	Numeric Data Display	Available
	Waveform Display	Available
	Trend Display	Available
	Harmonic Bar Display	Available
	Vector Graph Display Function	Available
Display	From the PC	Available
Types of Files	Conversion to CSV	Available
Data Acquisition Interval	50 ms at max. speed.	Available

You can use the software to control a single WT3000E that is connected to the PC.